

Hi, Jean

This means that whoever designed the rig put the sails (the center of effort,) too far forward. Either of the solutions you mention would work, as would moving the sails aft on their masts, or moving the masts farther aft. Obviously, moving the masts aft is both a big project and might well be very inconvenient for the accommodations. Putting a small mizzen aft would also fix the problem.

Regards, Tim at <http://bigcatcatamarans.com>

Cela signifie que, qui que soit le dessinateur du gréement, le centre d'effort de la voilure a été placé trop en avant, Chacune des 2 solutions mentionnées (réduire la misaine ou agrandir la GV) fonctionnera, ainsi que déplacer les voiles vers l'arrière des mats ou bien déplacer les mats vers l'arrière, Évidemment déplacer les mats est à la fois un gros travail et peut se révéler problématique pour les aménagements, Mettre un petit artimon (tape-cul) peut aussi régler le problème,